

Jobs List: 79 - Komatsu PC300 Excavator

VIN/Serial No: 81177

Location: 366 Burnside Road, Gilberton Qld 4208

Insert Service: -- No Selection --

- Show Prestarts
- Show Hire

Show Map

Add

Job Card	Description	Created	Completed	Priority	Parts Needed	Completed By
23919	GPS Components	25/07/19	25/07/19	Minor defects		Karl Massurit
23210	3250 hours service	11/07/19	16/09/19	Routine service		Karl Massurit
21985	Prestart Defect - Other issues to report Failed	13/06/19	31/07/19	Minor defects		Robert O'Leary
20021	Remove GPS radio	24/04/19	30/04/19	Routine service		Jordan Quest
19608	2750 hours service	16/04/19	16/04/19	Routine service		Warren Lyons
19582	Leaking fitting on tilt bucket OLPH968	15/04/19	16/04/19	Minor defects		Jordan Quest
18183	Machine inspection while on site doing service	26/03/19	26/03/19	Routine service		Ian Holm
18182	Possible hydraulic oil leak on slew lock pin cylinder - MONITOR	26/03/19	31/07/19	Minor defects		Robert O'Leary
17642	Slow leak on RHS of hammer R89 - see photo	19/03/19	19/03/19	Equipment ineffective		BA Equipment Fitter (Hammer)
17132	Hammer moyle broken - needs replacing ASAP	11/03/19	11/03/19	Equipment ineffective		BA Equipment Fitter (Hammer)
16409	2500 hours service	01/03/19	26/03/19	Routine service		Ian Holm
15309	Collect unused hammer grease & bring back to yard	13/02/19	07/03/19	Routine service		Warren Lyons
15193	Need 2 x new ratchet GPS handles	12/02/19	12/02/19	Minor defects		Jordan Quest
14837	Wash undercarriage for float	06/02/19	06/02/19	Minor defects		Jason Holm
14738	2 x Fire extinguishers need retesting by 28/2/19	05/02/19	14/02/19	Routine service		Jim's Test & Tag
14480	Flashing Light Globe Blown	01/02/19	05/02/19	Equipment ineffective		Jordan Quest
14387	Top up hydraulic oil	31/01/19	31/01/19	Minor defects		Ian Holm
14297	Tilt bucket #968 is missing 3x bolts & need new wear plates	30/01/19	08/02/19	Minor defects		Jason Holm
13297	2250 hours service	16/01/19	24/01/19	Routine service		Warren Lyons
11815	Blown a hose on hammer R89	11/12/18	11/12/18	Equipment ineffective		BA Equipment Fitter (Hammer)
11814	Swap out hammers	11/12/18	11/12/18	Routine service		BA Equipment Fitter (Hammer)
11541	Need hammer grease	07/12/18	07/12/18	Minor defects		Warren Lyons
10586	Hammer fittings on machine don't fit fittings on hammer HB38	26/11/18	26/11/18	Equipment ineffective		Ian Holm
10440	Tilt bucket #968 is missing a bolt - see photo	23/11/18	05/12/18	Minor defects		Ian Holm
9941	2000 hours service	17/11/18	23/11/18	Routine service		Komatsu Fitter
9712	Respray & touch up multiple scratches	14/11/18	04/06/19	To do when in workshop		Jordan Quest
8395	Clean machine for float	29/10/18	29/10/18	Routine service		Warren Lyons
8151	Tilt Bucket GET needs replacing	25/10/18	01/11/18	Routine service		Jordan Quest
8061	Mud bucket needs new cutting edge	24/10/18	01/11/18	Equipment ineffective		Jordan Quest
7601	Need 2 x new bolts of Tilt bucket #968	12/10/18	12/10/18	Equipment ineffective		Mick Gilmore
7246	GPS not working properly	05/10/18	05/10/18	Equipment ineffective		Sitech GPS
6515	1750 hours service	20/09/18	24/09/18	Routine service		Komatsu Fitter
6184	Tilt bucket bolts all gone on bucket #968	13/09/18	13/09/18	Equipment ineffective		Dean Pallett
5593	Hammer moyle snapped on HB38	31/08/18	05/09/18	Equipment breakdown		BA Equipment Fitter (Hammer)
5329	Retag & Retest 2 x fire extinguishers	24/08/18	05/09/18	Routine service		Mick Gilmore
5078	FAULTS NOTED DURING 1500 HR SERVICE 18/8/18	20/08/18	20/08/18	Minor defects		Komatsu Fitter
4475	1500 hours service	07/08/18	20/08/18	Routine service		Komatsu Fitter
3968	Tilt bucket #968 needs to be rebuilt	26/07/18	24/08/18	Equipment ineffective		RD Williams Fitter
3068	Bucket cylinder rod end needs shimming & missing foot pedal	25/07/18	25/10/18	Minor defects		Jordan Quest
2724	Prestart Defect - Check all attachments for damage and cracks	26/06/18	26/06/18	Minor defects		Dean Pallett
2723	Prestart Defect - Check all attachments for damage and cracks	26/06/18	26/06/18	Minor defects		
2571	1250 hours service	22/06/18	05/07/18	Routine service		Komatsu Fitter
1222	500 hrs Routine Service	21/05/18	21/05/18	Routine service		Komatsu Fitter
1221	1000 hours service	21/05/18	29/05/18	Routine service		Komatsu Fitter
1053	Cutting edge needs flipping	16/05/18	07/06/18	Minor defects		Dean Pallett
632	drop off hitch inspection form	01/05/18	01/05/18	Minor defects		Dean Pallett
258	Replace fire extinguishers	09/04/18	11/04/18	Equipment ineffective		Dean Pallett
155	750 hrs Routine Service	29/03/18	21/05/18	Routine service		Komatsu Fitter