

Original - To be handed to person presenting vehicle for inspection.  
 Duplicate - For - Retention copy  
 Triplicate - For - Book Copy

**vicroads**  
**Certificate Of Roadworthiness**  
 Road Safety (Vehicles) Regulations 2009, Victoria

Serial K 246466

TESTER'S LICENCE NUMBER EX 11951HV

**A WARNING - Any alteration makes this certificate invalid**

**Vehicle Description**

Registration Number 100 Legs Year 2011 Make Volvo  
 Model FH16 Colour BLUE Type PRIME MOVER  
 VIN/Chassis Number YV5AP00D5BD133780  
 Engine Number D16 053512  
 Signature of Licensed Tester OR Signature of Person authorized to give a certificate on behalf of Licensed Tester  
 Print Name Jason Spooce  
 Date (to be written) in words Twenty-Ninth of October 2019  
 Address at which Test Conducted  
6 Pinnacle Rd.  
ALTONA NTH.  
 Telephone 03 99311666

**B Test Report (Purchaser's Copy)**

**WARNING - This is not an assessment of the overall condition of the vehicle (See rear side for further information)**

Serial K 246466

Registered Number/VIN YV5AP00D5BD133780 Tester's Licence Number EX 11951HV  
 Examined and Tested for (name of person presenting vehicle)  
 Name Rodney G Williams Privacy statement on rear of form.  
 Address 4488 MOIRA LAKES RD. BARMAN VIC 3639  
 Contact Phone No. ( ) \_\_\_\_\_ Do not write in this space  
 Date of First Test 28-10-19 Time of First Test 3:00 Date of Second Test 29-10-19 Time of Second Test 12:30  
 Odometer Reading 1136236 Odometer Reading 1136237  
 Signature of examining mechanic conducting test Jason Spooce Signature of examining mechanic conducting test Jason Spooce  
 Print Name Jason Spooce Print Name Jason Spooce

1st	Tests	2nd	List Defects Found
<input checked="" type="checkbox"/>	Wheels and Tyres	<input checked="" type="checkbox"/>	Defecting worn Drive tyres.
<input checked="" type="checkbox"/>	Steering and Suspension	<input checked="" type="checkbox"/>	Defecting ABS fault on Dash.
<input checked="" type="checkbox"/>	Brakes	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Brake Performance	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Service Brake <u>529</u>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Parking Brake	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Seats and Seat Belts	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Lamps, Signals, Reflectors etc	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Exhaust and Emission Controls	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Windscreen and Windrow	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Windscreen Wipers, Washers, etc	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Body and Chassis	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Engine and Driveline	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Other Items	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Modifications	<input type="checkbox"/>	